



STATE OF HAWAII
DEPARTMENT OF EDUCATION
KING LIHOLIHO ELEMENTARY SCHOOL
3430 MAUNALOA AVENUE
HONOLULU, HAWAII 96816

HONOLULU DISTRICT

February 26, 2019

Dear Parents/Guardians, Students, Teachers and Staff,

The Asbestos Hazard Emergency Response Act (AHERA) requires all schools to be inspected to identify any asbestos-containing materials. The law further requires a management plan based upon the findings of the initial inspection and six month surveillance inspections thereafter. Such an inspection has recently been completed in our school.

There have been no changes in the condition of the asbestos-containing materials identified in our buildings since the last Re-Inspection Report.

A copy of the school's management plan as well as the inspection report is available to review in the school's office.

Sincerely,

Christina Small

Principal