

A large circular inset image showing the interior of a building under construction. The structure consists of a complex network of dark steel beams and supports. The ceiling is made of corrugated metal panels, with several rectangular skylights allowing natural light to enter. The overall scene is industrial and shows the skeletal framework of a large structure.

MEASURE AA CONSTRUCTION UPDATE

FACILITIES DEPARTMENT

SEPTEMBER 19, 2019

Branham Two Story Classrooms



Westmont High School New Campus Entrance



Leigh HS Swimming Pool



Del Mar HS Swimming Pool

