

**Hardin Park
High School Baseball – Softball Field**

602 Crescent Street

Town Administrator Todd Smith

Assessment October 23, 2018



LOCATION SUMMARY

A sixty-five acre park that features an Olympic-sized swimming pool with attached bathhouse, 2 playgrounds, fishing pond, 6 covered pavilions, picnic tables, 3 baseball fields, 2 softball fields, 4 tennis courts, outdoor basketball court, a skatepark, and a walking track/trail. The park also houses the maintenance shop and staff. The maintenance area is comprised of two office buildings, 2 garages, and a storage facility.

Responsible for Hardin Park ADA Transition Plan Section

Director Butch Patterson – 423-638-3143 / bpatterson@greenevilletn.gov

Office Manager/Program Supervisor Lisa Scott Fisher – 423-638-3143 / lfisher@greenevilletn.gov

Maintenance Director John Darnell – 423-823-0720 / jdarnell@greenevilletn.gov

ADA Checklist for Existing Facilities

Priority 1 – Approach & Entrance

Based on the 2010 ADA Standards for Accessible Design



Project: ADA Assessment Greeneville, TN

Building: High School Baseball/Softball Fields
And Noon Rotary Club Field

Location: Hardin Park

Date: Oct 9 2018

Surveyors: Dave Wright, Gail Stacy, Caroline Miller

Contact Information: 423-525-5093

An accessible route from site arrival points and an accessible entrance should be provided for everyone.

Priority 1 – Approach & Entrance		Comments	Possible Solutions
<p>1.1 Is there at least one route from site arrival points (parking, passenger loading zones, public sidewalks and public transportation stops) that does not require the use of stairs? [See 2010 ADA Standards for Accessible Design – 206.2.1]</p>	<p>No accessible route No accessible parking</p>	 <p>Photo #:</p>	<ul style="list-style-type: none"> • Design access • Design accessible parking <p>Budget Year: 2020 Cost: \$12,500</p>
Exterior Accessible Route			
<p>1.13 Is the route stable, firm and slip-resistant? [302.1]</p>	<p>No accessible route</p>	 <p>Photo #:</p>	<ul style="list-style-type: none"> • Design access • Design accessible parking <p>Budget Year: 2020 Cost: \$20,000</p>

Entrance

1.37 Is the main entrance accessible?

No

Photo #:

- Redesign to make it accessible
- Refer to 1.13

1.38 If the main entrance is not accessible, is there an alternative accessible entrance?

No




Photo #:

- Designate an entrance and make it accessible
- Refer to 1.13

Seating: Assembly Areas – theaters, auditoriums, stadiums, theater style classrooms, etc.

2.52 Are an adequate number of wheelchair spaces provided? [221.2.1]

No

Total #:

Wheelchair #: 0

# of Seats	Wheelchair Spaces
4 - 25	1
26 - 50	2
51 - 150	4
151 - 300	5
300+ see 2010 Standards 221.2.1.	

Photo #:

- Reconfigure to add wheelchair spaces
- Refer to 1.13

Sales & Service Counters – banks, stores, dry cleaners, auto repair shops, fitness clubs, etc.

2.76 Is there a portion of at least one of each type of counter that is:

No higher than 36 inches above the floor?

At least 36 inches long?
[904.4.1]

No
Measurement:

Yes
Measurement:




Photo #:

- Lower section of counter

Budget Year: 2020
Cost: \$1,000

Priority 3 – Toilet Rooms

Comments

Possible Solutions

3.1 If toilet rooms are available to the public, is at least one toilet room accessible? (Either one for each sex, or one unisex.)

Note: If toilet rooms are chiefly for children, e.g., in elementary schools and day care centers, use the children’s specifications in Toilets - 604.1, 604.8, 604.9, 609.4 and Lavatories and Sinks – 606.2.

No
toilets not
accessible

Refer to 1.13

Photo #: