

Public Notification
Of
Asbestos Management Program

State and federal asbestos regulations require that building occupants be notified about asbestos management activities and the existence of the Asbestos Management Plan (AMP).

The Windham Public Schools facilities have been inspected to determine the presence of asbestos and to evaluate the potential for human exposure to airborne fibers. As is the case for most schools, asbestos-containing products were found in our school buildings.

Wherever the potential exists for damaged materials to cause asbestos fibers to be released into the air, we have encapsulated or enclosed the material. Most of the materials that present a potential for exposure are in areas that are inaccessible to students, such as boiler rooms and pipe tunnels.

An Asbestos Management Program has been developed to maintain these materials in a condition in which they do not pose a health hazard. As part of this program, asbestos-containing materials are inspected several times each year and the Asbestos Management Program are re-evaluated every three years.

Anyone wishing to know more about the Asbestos Management Program or the asbestos containing materials found in our schools should ask to see the Asbestos Management Plan, which is on file in the main office of each building and in the Buildings & Grounds office. Any questions may be addressed to Windham Public Schools, Director of Facilities, 355 High Street Unit B, Willimantic, CT 06226, 860-465-2335.

Notificación Pública

Sobre

El Programa de Administración de Asbestos

Las reglas estatales y federales requieren que los ocupantes de edificios queden notificados sobre las actividades de administración de asbestos y la existencia del Plan de Administración de Asbestos (AMP).

Las instalaciones de las Escuelas Públicas de Windham han sido inspeccionadas para determinar la presencia de asbestos y para evaluar el potencial de exposición humana a las fibras en el aire ambiental. Como es el caso en la mayoría de escuelas, productos que contienen asbestos fueron encontrados en los edificios de nuestras escuelas.

Hemos encapsulado todo material con el potencial existente de liberar fibras de asbestos en el aire. La mayor parte de los materiales que presentan un potencial de exposición están localizadas en áreas que no son accesibles para los estudiantes, como los cuartos de calderas y los túneles de plomería.

Se ha desarrollado un Programa de Administración de Asbestos para mantener estos materiales en condiciones las cuales no causan daños a la salud. Como parte de este programa, los materiales que contienen asbestos son inspeccionados varias veces al año y el Programa de Administración de Asbestos es reevaluado cada tres años.

Toda persona que desee saber más sobre el Programa de Administración de asbestos o los materiales que contienen asbestos en nuestras escuelas debe pedir ver el Plan de Manejo de Asbesto, lo cual está en el archivo de la oficina principal de cada edificio, y en la oficina de Edificios y Terrenos. Cualquier pregunta puede dirigirse a las Escuelas Públicas de Windham, Director de Facilidades, 355 High Street Unit B, Willimantic, CT 06226, 860-465-2335.