

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>CESQ3111/CESQ3112</b>	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number <b>005096745 JJK</b>	
5. Generator's Name and Mailing Address <b>Wink-Loving ISD 200 N Rosey Dodd Ave Wink TX 79789</b>			Generator's Site Address (if different than mailing address) <b>Old High School Auditorium BLDG 200 N Rosey Dodd Ave Wink TX 79789</b>			
6. Transporter 1 Company Name <b>Vanco Insulation, Inc</b>		U.S. EPA ID Number <b>400294</b>				
7. Transporter 2 Company Name		U.S. EPA ID Number				
8. Designated Facility Name and Site Address <b>Charter Waste Landfill 12035 W Murphy Odessa TX 79765</b>					U.S. EPA ID Number <b>H2158</b>	
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		No.	Type			
1.	<b>RQ Asbestos 9 UN P6 III</b>					
2.	<b>Friable 34121418560</b>					<b>CESQ3111</b>
3.	<b>NON Friable 3412149458</b>	<b>640</b>	<b>bg</b>	<b>10</b>	<b>gds</b>	<b>CESQ3112</b>
4.						
14. Special Handling Instructions and Additional Information <b>Disposal must be in accordance with TDHMWR 125-136 "B", 6 or other handling plan approved in writing by TDHMWR</b>						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition, for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offoror's Printed/Typed Name <b>RANDALL ELKINS FOR owner</b>				Signature <i>Randall Elkins</i>		Month Day Year <b>11/18/19</b>
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name <i>Bradley Coan</i>				Signature		Month Day Year
Transporter 2 Printed/Typed Name				Signature		Month Day Year
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number: _____						
18b. Alternate Facility (or Generator)					U.S. EPA ID Number	
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)					Month Day Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.	2.	3.	4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name <b>CT Arnold</b>				Signature <i>CT Arnold</i>		Month Day Year <b>12/1/19</b>

GENERATOR

TRANSPORTER INTL

DESIGNATED FACILITY