

ISBE ID	Building ID	Building Description	Sample Date	Sample Time (12 HR Clock)	Collected By	Sample ID Number	Sample Location Description	Fixture Type	Date of Last Use	Time of Last Use (12 HR Clock)	Sample Type	Sample Volume (mL)	Laboratory Name	Analytical Method	Concentration (ug/L)	Reporting Limit (ug/L)	Notes
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-25a	Classroom 6 B Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-25b	Classroom 6 B Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-26a	Classroom 6 Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-26b	Classroom 6 Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-27a	Classroom 2 B Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Initial Test - Source Mitigated - WB
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-27b	Classroom 2 B Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	10.20	0.10	Initial Test - Source Mitigated - WB
14-016-0930-2001	HES	Hillside ES	2/8/18	6:30 AM	IL 001047	HES-27aR	Classroom 2 B Sink	S - Sink	2/7/2018	7:00 PM	First Draw	250	STAT Analysis	EPA 200.8	57.90	2.00	Re-Test - see HE-01 & HE-02
14-016-0930-2001	HES	Hillside ES	2/8/18	6:30 AM	IL 001047	HES-27bR	Classroom 2 B Sink	S - Sink	2/7/2018	7:00 PM	Flush	250	STAT Analysis	EPA 200.8	<2.00	2.00	Re-Test - see HE-01 & HE-02
14-016-0930-2001	HES	Hillside ES	4/26/18	6:30 AM	IL-1001892	HE-01	Classroom 2 B Sink	S - Sink	4/25/2018	7:00 PM	First Draw	250	STAT Analysis	EPA 200.8	<2.00	2.00	2nd Re-Test Result after Mitigation-WB
14-016-0930-2001	HES	Hillside ES	4/26/18	6:30 AM	IL-1001892	HE-02	Classroom 2 B Sink	S - Sink	4/25/2018	7:00 PM	Flush	250	STAT Analysis	EPA 200.8	<2.00	2.00	2nd Re-Test Result after Mitigation-WB
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-28a	Classroom 2 Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-28b	Classroom 2 Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-29a	Classroom 1 B Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-29b	Classroom 1 B Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-30a	Classroom 1 Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-30b	Classroom 1 Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-31a	Classroom 4 B Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-31b	Classroom 4 B Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Wash Basin
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-32a	Classroom 4 Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-32b	Classroom 4 Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-33a	Classroom 3 B Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	2.30	0.10	Initial Test - Source Mitigated - WB
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-33b	Classroom 3 B Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Initial Test - Source Mitigated - WB
14-016-0930-2001	HES	Hillside ES	2/8/18	6:30 AM	IL 001047	HES-33aR	Classroom 3 B Sink	S - Sink	2/7/2018	7:00 PM	First Draw	250	STAT Analysis	EPA 200.8	<2.00	0.10	Re-Test Result following Mitigation -WB
14-016-0930-2001	HES	Hillside ES	2/8/18	6:30 AM	IL 001047	HES-33bR	Classroom 3 B Sink	S - Sink	2/7/2018	7:00 PM	Flush	250	STAT Analysis	EPA 200.8	<2.00	0.10	Re-Test Result following Mitigation -WB
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-34a	Classroom 3 Sink	S - Sink	11/9/2017	8:00 PM	First Draw	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink
14-016-0930-2001	HES	Hillside ES	11/10/17	5:00 AM	IL 001047	HES-34b	Classroom 3 Sink	S - Sink	11/9/2017	8:00 PM	Flush	250	Pace Labs	EPA 200.8	<2.00	0.10	Sink

R = Right

L = Left

ND = None Detected

BFS = Bottle Filling Station